

Ag Leader® ISO Liquid Rate Control

Ag Leader Technology is pleased to announce the release of new firmware. Features and improvements in this version are listed below. This free upgrade is available for download from <http://www.agleader.com>.

IMPORTANT!

- A. It is recommend that a backup be created prior to upgrading display firmware

[New in 1.16](#)

General

- **FIXED:** PWM Valve Control
- **FIXED:** Issue with WSM Getting into Crash Loop

[New in 1.15](#)

General

- **FIXED:** Faulty Auxiliary Valve Control

[New in 1.14](#)

General

- **FIXED:** Auxiliary input speed rounding
- **FIXED:** False Pressure/Flow Relationship message in calibrated reflow systems